



December 22, 2010

MR. JAY JOSEPH SENIOR MANAGER, PRODUCT REGULATORY OFFICE AMERICAN HONDA MOTOR CO. 1919 TORRANCE BLVD. TORRENCE, CA 90501 NVS-215dgl 10V-640

SUBJECT: FRONT SUSPENSION DAMPER BOLTS AND SPINDLE NUTS

DEAR MR. JOSEPH:

This letter serves to acknowledge American Honda Motor Co.'s (Honda) notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall campaign which will be conducted pursuant to Federal law for the vehicles listed below.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HONDA/ACCORD/2010-2011 HONDA/PILOT/2011

NHTSA Campaign Number: 10V-640

Mfg's Report Date: December 16, 2010

Components: SUSPENSION

Potential Number of Units Affected: 10,823

Summary:

HONDA IS RECALLING CERTAIN MODEL YEAR 2010-2011 HONDA ACCORD V6 AND MODEL YEAR 2011 HONDA PILOT VEHICLES. THE BOLTS THAT ATTACH THE LOWER LEFT AND RIGHT FRONT DAMPER BRACKET TO THE FRONT SUSPENSION AND THE SPINDLE NUTS ON THE PILOT MAY NOT HAVE BEEN PROPERLY TIGHTENED WHICH MAY RESULT IN LOSS OF STEERING. THE SPINDLE NUTS FOR THE AXLE ON THE ACCORD V6 MAY NOT HAVE BEEN TIGHTENED PROPERLY WHICH MAY RESULT IN EXCESSIVE NOISE AND/OR LOSS OF STEERING.

Consequence:

LOSS OF STEERING INCREASES THE RISK OF A CRASH.

Remedy:

DEALER WILL INSPECT AND REPLACE ANY LOOSE FRONT DAMPER BRACKET BOLTS OR SPINDLE NUTS ON THE PILOT IF NECESSARY. DEALER WILL INSPECT AND REPLACE THE SPINDLE NUTS ON THE ACCORD V6 IF NECESSARY. THE SAFETY RECALL IS EXPECTED TO BEGIN ON OR BEFORE DECEMBER 23, 2010. OWNERS MAY CONTACT HONDA AT 1-800-999-1009.

Notes:

HONDA'S SAFETY RECALL NO. R60. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO HTTP://WWW.SAFERCAR.GOV.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

We have reviewed your proposed owner notification letter and it meets the requirements of Part 577.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contact for this recall will be Delia Lopez who may be reached by phone at 202-366-9525, or by email at Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you toward a successful completion of this recall campaign.

Sincerely,

Jennifer Timian

Chief, Recall Management Division

Office of Defects Investigation

Enforcement